


MK6 (Zephyr) Diff Carrier Cleanup

Operations -

- 1) remove material
- 2) new ring mtg holes



Hub centering jig exists

